

FIG. 1




FIG. 3

FIG. 2




FIG. 5




FIG. 4




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 15




FIG. 14




FIG. 16

5/23




FIG. 17

FIG. 18




FIG. 19




FIG. 20




FIG. 21

6/23




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27






FIG. 29

FIG. 28




FIG. 31

FIG. 32






FIG. 52




FIG. 51

10/23




FIG. 30




FIG. 33







FIG. 34




*FIG. 36*




*FIG. 37*




*FIG. 38*



*FIG. 39*



*FIG. 40*



*FIG. 35*




FIG. 42




FIG. 41




FIG. 43




FIG. 44




FIG. 45




FIG. 46







Fig. 10 is a perspective view of a second embodiment of the connector. It shows a similar L-shaped profile with a circular feature labeled 660 on the top surface of the vertical leg. The internal structure of the horizontal leg is different from Fig. 9, featuring a series of rectangular protrusions.

[illegible]

FIG. 50





FIG. 53



*FIG. 54A*

*FIG. 54*




FIG. 55




FIG. 56




FIG. 57




FIG. 58




FIG. 59